

DJI P1 Release Notes

Release Date: 2021.05.10

DJI P1 Firmware: v02.04.01.02

Firmware Upgrade Method: DJI P1 - SD card / Update All in App

Other Product Firmware and M300 RTK aircraft firmware: v02.04.01.02

M300 RTK remote controller firmware: v02.04.01.03

Software Required:

DJI Pilot App Android: v2.4.1.7 (M300)

What's New?

• Added lens activation. Activation will be triggered after firmware is updated.

• Added one second timed shot in DJI Pilot when taking photos manually.

• Added Oblique GSD in DJI Pilot.

• Optimized resumption of interrupted flight route tasks in Smart Oblique. Aircraft will return to break point and adjust to flight speed and complete shooting sequence of previous waypoint.

- Optimized camera exposure compensation to improve exposure accuracy of entire flight route.
- Improved calculation accuracy of frontal overlap ratio in Smart Oblique.
- Optimized estimation of photo numbers and flight time in Smart Oblique.
- Fixed issue: white spots appeared in corners of DNG photos.
- Fixed some minor bugs.

Notes

- Follow steps to activate lens when prompted in DJI Pilot.
- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.



DJI P1 Release Notes

Release Date: 2021.03.11

DJI P1 Firmware: v02.02.03.02

Firmware Upgrade Method: DJI P1 - SD card / Update All in App

Other Product Firmware and M300 RTK aircraft firmware: v02.02.02.01

M300 RTK remote controller firmware: v02.02.01.02

Software Required:

DJI Pilot App Android: v2.2.1.7

What's New?

• Reduced motion blurring that occasionally occurred when shooting some photos in Smart Oblique.

- Reduced screen blurring and freezing during video transmission in Smart Oblique.
- Fixed occasional issue: false gimbal overload warning prompt was sent.

Notes

• Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.